



09575551

Attorney Docket No. 54008.8009.US02
P97-0041US3

For [Signature]
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Raymon F. Thompson et al.

U.S. PATENT NO.: 6,833,035

ISSUED: DECEMBER 21, 2004

FOR: SEMICONDUCTOR PROCESSING
SYSTEM WITH WAFER CONTAINER
DOCKING AND LOADING STATION

REQUEST FOR CERTIFICATE OF CORRECTION

UNDER 37 C.F.R. § 1.322

Attn: Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

1. Applicants request a Certificate of Correction to correct the following error in the above-identified patent, which error is listed on the enclosed Form PTO/SB/44.
2. The requested correction does not constitute new matter or require reexamination of the patent.
3. The error listed on Form PTO/SB/44 is believed to be due to mistake on the part of the USPTO (37 C.F.R. § 1.322). Accordingly, no fee is believed to be due.

Certificate of Mailing

I hereby certify that this paper (along with any referred to as being attached or enclosed) is being deposited with the United States Postal Service on the date shown below with sufficient postage in an envelope addressed to Attention: Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

March 25, 2005

Date of Deposit

Amy Shields
Amy Shields

4. Please send the Certificate of Correction to the undersigned at the address shown below.

Dated: March 25, 2005

Customer No. 34055
Perkins Coie LLP
Patent - LA
P.O. Box 1208
Seattle, WA 98111-1208
Phone: (310) 788-9900
Fax: (310) 788-3399

Respectfully submitted,

PERKINS COIE LLP

By: Kenneth H. Ohriner
Kenneth H. Ohriner
Reg. No. 31,646

Under the paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,833,035

DATED: December 21, 2004

INVENTOR(S) Raymon F. Thompson, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

On the cover page of the patent, item (75), replace "Raymond F. Thompson" with
--Raymon F. Thompson--.

MAILING ADDRESS OF SENDER:

Customer Number 34055
Perkins Coie LLP
P.O. Box 1208
Seattle, WA 98111-1208
Phone: (310) 788-9900

PATENT NO. 6,833,035

No. of additional copies

0

Burden Hour Statement: This form is estimated to take 1.0 hours to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.